

Office of Sub Divisional Officer P.W.D. (B&R) Banda
Sub Division Banda

Memo No. 116

SDC/ Banda

Dt. 15-3-2023

To ,

The Principal
St. Joseph Sr. Sec. School
Village Jamuniya Tehsil Banda
Distt. Sagar MP

Sub: Building Safety certificate of the school building.

Ref.: Your letter dated 13/03/2023

Kindly find enclosed herewith the Fitness certificate of St. Joseph Sr. Sec. School, Banda building as required.

The School building was inspected by undersigned on 15/03/2023 in reference to above letters. The building is in good conditions and ready to start classes. Hence, the fitness Certificate is being issued.

Encl.: Fitness certificate


Sub Divisional Officer
PWD(B&R)
Sub Divisional Officer
P.W.D. Sub Div. Banda
Banda Sub Division Banda

Fitness Certificate

1. Name of Building St. Joseph Sr. Sec. School, Village Jamuniya Tehsil
Banda Distt. Sagar, MP.
2. Name of Inspecting Officer 1- S.K. Mishra, SDO PWD Banda
2- Sanjay Chaturvedi , Sub Engineer
3. Date of Inspection 15/03/2023
4. Details of Building As mentioned in the drawing provided –
Foundation - Column Footing
RCC work - 1:2:4 M 15 grade
Walls - Brick masonry 1:6, 20cm thick
Plaster - CM 1:5
Flooring - IT and Kota stone flooring
Roof - RCC 1:2:4 M 15 grade concrete
No. of floors - G+2
Year of Construction – 2019
Note : Above mentioned date has been provided by
the school
5. Period for which the certificate is issued Two year from the date of inspection for G + 2 RCC
Structure
6. Nature of defects, if any The building is G+2 RCC Structure. No structure crack
has been observed.
a) Foundation - RCC column footings
b) Super structure - RCC column and beams with brick
partition masonry
c) Doors and Windows – Iron
d) Roof - RCC 1:2:4 M grade concrete
7. Any major defects noticed which will render the building unsafe in any manner The building is safe for school purpose for the period
of certification for three floor.

8. Whether the maintenance work have been done properly The building is newly constructed and maintenance is good
9. Whether the Structure is sound or not for the purpose of use G+2 structure is sound enough to conduct classes
10. Any other observation if deemed necessary Nil

CERTIFICATE : Certified that school building was inspected by me on 15/03/2023 found to be suitable to conduct classes for the period of Two years for the stated above.

Place : Banda
Date : 15/03/2023


Sub Divisional Officer
PWD(B&R)
Banda Sub Division Banda
Sub Divisional Officer
P.W.D. Sub Div. E